

Hydrant Inspection Report

Docket No. 01-0488

ICC Staff Exh. 1.01

pg. 1 of 2

System: Crystal Clear Water Company

		1997	2001	
Hydrant #	Location	Gals. per min.	Gals. per min.	Comments
1	Behind Around the Clock	450	530	a) Raise Hyd. to 18 inches;
				b) Hydrants requires painting;
8	Redwood St. & Claire St.			Not operating - same
				a) Repair broken operating pentagon
				b) Repair frozen steamer port
6	Three Oaks Rd. & Redwood St.	550	715	a) Raise Hyd. to 18 inches; Chlorine free - .7;
				b) Repair steamer port
				c) Chlorine (free) - .7 mg/l
4	Colonial St. & Rose St.	530	590	a) Hydrant requires painting;
3	Cowlin St. & Colonial St.	370	No flow test	Replace missing hydrant
2	Manor Rd. & RT. 14	530	675	a) Hydrant requires painting;
				b) install missing chains;
				c) repair pentagon
5	Drive in Lane	600	840	a) Hydrant requires painting;

Note:

No change from last inspection

Hydrant Inspection Report

Docket No. 01-0488

ICC Staff Exh. 1.01

System: **Crystal Clear Water Company**

pg. 2 of 2

[illegible]